

Firmware Release Notes

Entrust Desktop Printer Firmware

This document provides a summary of the new features and updates to the Sigma DS and EM Series Direct to Card Printers firmware.

Version Information

Firmware Version	D4.2.5
Release Date	May 2023
Update of Released Version	D4.2.4
Component Versions:	
• Printer	D4.2.5-6
Printer BSP	D4.1.21-14
Embosser Firmware Version	E1.1.54-3
Laminator Firmware Version	L1.1.6-16
• TIM Impresser Firmware Version	11.1.3-2
RIM Indenter Firmware Version	N1.1.2-2
LCM UV Cure Firmware Version	V1.1.0-9
Multi-hopper Firmware Version	M1.3.0-2
OpenCard Plug-in Version	PLG.1.31-3
Smart Card Coupler	DE-ABCM5_CCID_DC_230418

D4.2.5 Firmware Release

Improvements

- Duali ABCM5 coupler firmware updated to address field issues with Thales R12 and MIFARE.
- Printer dashboard updated to print a double-sided test card when duplex ribbon is installed.
- The robustness of embosser supplies tag reading and writing process has been improved.
- Improved reporting of jammed cards and lost cards.
- Added a setting to allow disabling an embosser move during card exit that occasionally causes a 131 error on some embossers.
- Fixed an issue with One-Click firmware update from Printer Dashboard. D4.2.5 firmware must still be updated using the update utility. Once D4.2.5 is installed, future updates will once again be available using the One-Click feature.

Security

- Printer operating system updated to LTS 21 RCPL 16.
- Updated OpenSSL to resolve CVE-2023-0286