



Firmware Release Notes

Entrust Desktop Printer Firmware

This document provides a summary of the new features and improvements to the Entrust SD, CD, and CE Series desktop printers that currently run version D3.17.1 or newer firmware and are not enabled for OpenCard.

Component Version Changes

Firmware Version	D3.19.2
Release Date	April 2023
Update of Released Version	D3.19.1-SP1
Component Versions:	
• Printer	D3.19.2-2
• Printer BSP	D3.19.1-4
• Embosser Firmware Version	E1.1.54-1
• Laminator Firmware Version	L1.1.6-15
• DUALi Smart Card Coupler	DE-ABCM_L_DC2_211006_CCID_PCSC
• HID Omnikey Smart Card Coupler	HID Global 5127 CK 01000069

D3.19.2 Firmware Release

D3.19.2 adds support for updated embosser components. **Once updated, printers with embossers cannot be downgraded to firmware versions earlier than D3.19.2.**

Security Updates

- Boot-time security enhanced.

Improvements

- Added setting to choose single-wire Duali coupler firmware update logic (leave as-is or force to match version in printer firmware). OMNIKEY coupler firmware will always be left as-is regardless of the setting.

Resolved Issues

- The YMC color power displayed on the printer's front panel will now display the correct value after it has been changed using the front panel buttons.

Notes

- Printers enabled for OpenCard cannot be updated to D3.19.x. They must remain at the D3.18.x firmware level.