



ENTRUST

Release Notes

Entrust Desktop Retransfer Printer Firmware

This document provides a summary of a release to the desktop retransfer printer firmware.

Version Information

| | |
|----------------------------------|-----------------------------|
| Firmware Version | R4.10.5-2 |
| Release Date | November 2022 |
| Component Versions: | |
| • Printer Application | R4.10.5-2 |
| • Printer BSP | R4.1.15-1 |
| • Embosser Firmware Version | E1.1.51-1 |
| • Laminator Firmware Version | L1.1.6-15 |
| • Laser Firmware Version | Z1.1.0-302 |
| • Multi-hopper Firmware Version | M1.2.1-0, M2.2.1-0 |
| • Impresser Module | I1.1.1-6 |
| • Smart Card Coupler | DE-ABCM_L_DC2_200108_CCID_D |
| • HID Omnikey Smart Card Coupler | HID Global 5127 CK 01000069 |

Affected Printers

- Entrust Artista® CR805 Retransfer Printer
 - Entrust Artista® CR803 Retransfer Printer
 - Entrust Artista® CR825 and CE875 Instant Financial Issuance Systems
-

R4.10.5 Firmware Release

R4.10.5 adds support for updated multi-hopper components. **Once updated, printers cannot be downgraded to firmware versions earlier than R4.10.5.**