



Firmware Release Notes

Entrust Desktop Printer Firmware

This document provides a summary of the new features and improvements to the Entrust SD, CD, and CE Series desktop printers that currently run version D3.17.1 or newer firmware and are not enabled for OpenCard.

Component Version Changes

Firmware Version	D3.19.1-SP1
Release Date	October 2022
Update of Released Version	D3.19.1
Component Versions:	
• Printer	D3.19.1-5000
• Printer BSP	D3.19.1-4
• Embosser Firmware Version	E1.1.53-1
• Laminator Firmware Version	L1.1.6-15
• DUALi Smart Card Coupler	DE-ABCM_L_DC2_200108_CCID_D
• HID Omnikey Smart Card Coupler	HID Global 5127 CK 01000069

D3.19.1-SP1 Firmware Release

Resolved Issues

- A printer without a print head running D3.19.1-4 firmware will lock up when its settings are retrieved.

Notes

- Printers enabled for OpenCard cannot be updated to D3.19.1-SP1. They must remain at the D3.18.x firmware level.